



Bob Riley
GOVERNOR

**ALABAMA
DEPARTMENT OF TRANSPORTATION**

AERONAUTICS BUREAU
1409 COLISEUM BOULEVARD
MONTGOMERY, ALABAMA 36110
PHONE (334) 242-6820
FAX (334) 353-6540



Joe McInnes
TRANSPORTATION DIRECTOR

August 27, 2010

The Honorable William Latham
Pickens County Commission
Post Office Box 460
Carrollton, Alabama 35447

**Subject: Reinspection Report
North Pickens Municipal Airport**

Dear Mr. Latham:


An inspection of the North Pickens County Airport was conducted by personnel of the Alabama Department of Transportation Aeronautics Bureau on August 24, 2010. The purpose of the inspection was to update the information currently on file regarding the airport and to ascertain compliance with the rules and regulations of the Alabama Department of Transportation governing licensed public-use airports within the State of Alabama.

The inspection was conducted to verify that the license violations found during the Annual Inspection of August 11, 2010 had been corrected. The inspection determined that all license requirements have been met. The license to operate the airport is issued in full effect. The Code of Alabama 23-1-375 prohibits the operation of an airport for which a license has not been issued.

The Bureau thanks you for your prompt response in addressing these licensing issues.

If you should have any questions concerning the inspection or corrective actions, please do not hesitate to contact the Aeronautics Bureau at (334) 242-6820.

Sincerely,


John C. Eagerton IV, D.P.A.
Chief, Aeronautics Bureau

Copy: Mr. Rans Black
FAA/ADO

Mr. Ryan Sisemore, P.E.
Garver Engineers